# WSJT-X/FT-450/Rig-Blaster Advantage.

```
Set the radio: RTS = OFF
              CAT RATE = 9600
              CAT TOT = 10
```


On the RigBlaster set the switch to "COM"

If all has gone well, the "TEST CAT" should turn green..

Gary/M0TIG